



MORPCA Policy # 01
Engine Coolant Leak
Effective Date: January 8, 2018

Who is Affected:

HPDE Participants with Porsche automobiles limited to models "GT2", "GT3", "RS" and "Turbo" in the "996" and "997" series produced between 2001 and 2012 with the GT-1 style Mezger engine block.



Purpose of the Policy:

To reduce the risk to all the participants in a MORPCA sponsored High Performance Driving Event due to the known potential for an unintended coolant leak in certain affected automobiles.

Requirement:

No affected automobile is permitted to participate in any MORPCA High Performance Driving Event without a repair consisting of either 1) pinning the eight (8) coolant tubes or 2) welding the eight (8) coolant tubes to their casting. Series 997 affected models are also required to replace the two (2) plastic coolant elbow connectors that have double O-rings. Proof of a repair must be submitted, if requested, prior to the event.

John Peacock, DE Chair (de@morpca.org)