

2020 MORPCA MO HPDE Tech Instruction's

All drivers will need to show their helmet and turn in their completed Tech form at the time of registration. Drivers will receive a Tech sticker that will need to be completed by another driver and placed on the driver's side top or bottom corner of the windshield. * NO CAR WILL BE ALLOWED ON TRACK WITHOUT A FILLED-OUT TECH STICKER ON THE WINDSHIELD. Below are the instructions and what shall be looked at.

Instructor

1. Will receive two stickers in their packet. One for their car and one for their student. Instructor will be responsible for the Tech items on the sticker and will sign off on the Tech for the student driver.
2. The Instructor will have another driver sign off on their Tech sticker.

Yellow Student

1. Instructor will have your Tech sticker and will sign off on your Tech.

Blue, Red, White and Orange driver's

1. You will receive a Tech sticker in your packet and will need another driver to Tech and sign off on your Tech sticker.

Check-off Items

1. Restraints Verified- Make sure harnesses are in good working condition. On after-market 5-, 6-, and 7-point harnesses, check the date on harness to make sure they are not outdated. Ensure that a head-and-neck restraint is used with after-market harnesses.
2. No Loose Items In Car- Make sure floor mats and any other loose items are removed before going out on track.
3. Tires / Wheels / Brakes Checked- Make sure tires are in good condition with no sidewall damage. Check the torque on the wheels. Brake pads should be 3/16" minimum. If in question, MORPCA will have a brake lining thickness gauge on site. Check condition of brake fluid. If in question, MORPCA will have a moisture tester on site. Check to make sure brake lights are working. While under the hood check to make sure positive side of battery is covered.
4. Gas Cap Secure- Make sure gas cap is present and tight.